

<b>PCN Number:</b>	20151207000	<b>PCN Date:</b>	12/18/2015
<b>Title:</b>	Datasheet for DRV8303		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification etc.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



**DRV8303**

SLOS846B – SEPTEMBER 2013 – REVISED NOVEMBER 2015

Changes from Revision A (October 2013) to Revision B	Page
• Added ESD Ratings table, Feature Description section, Device Functional Modes, Application and Implementation section, Power Supply Recommendations section, Layout section, Device and Documentation Support section, and Mechanical, Packaging, and Orderable Information section .....	1
• Updated title .....	1
• V <sub>PVDD</sub> absolute max voltage rating reduced from 70 V to 65 V .....	5
• Clarification made on how the OCP status bits report in <i>Overcurrent Protection (OCP) and Reporting</i> .....	15
• Update to PVDD undervoltage protection in <i>Undervoltage Protection (UVLO)</i> describing specific transient brownout issue. ....	16
• Update to EN_GATE pin functional description in <i>EN_GATE</i> clarifying proper EN_GATE reset pulse lengths. ....	17
• Added gate driver power-up sequencing errata .....	22

The datasheet number will be changing.

Device Family	Change From:	Change To:
DRV8303	SLOS846A	<b>SLOS846B</b>

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/DRV8303>

#### Reason for Change:

To more accurately reflect device characteristics and identify issues with specific application conditions.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. There are no changes to the actual device. This is a specification change and errata announcement only. Update made to PVDD absolute maximum rating and in identifying device issues with specification conditions. Review datasheet for detailed information.

#### Changes to product identification resulting from this PCN:

None.

<b>Product Affected:</b>	
DRV8303DCA	DRV8303DCAR

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>