



Irregularly-shaped holes manufacture process


General tolerance: ±0.05





Note:

- 1. Solder balls may present on bottom side of the PCBA after reflow soldering. Washing & cleaning is recommended to remove debris.
- 2. Some additional hand soldering may be required after reflow.



Thickness = 0.12mm

Part Number			Product Description						
USB3190			Micro USB Receptacle, Type B, Surface Mount,						
Drawing Date			Vertical, Low Profile						
31st July 2020									
Ву	CC	Tolerances (E		<u></u>		This drawing is confidential and			
Detail	Drawing Release	X.X ± 0.30 X.XX ± 0.20 X.XXX ± 0.10	Angle	Metric (mm)	ROHS	©	copyright of Global Connector Technology, Ltd (GCT). This drawing must not be copied or disclosed without written consent. F & OF	www.g	
Revision	A2 12/10/20		-	3rd Angle Projection	2011/65/EU Deca-BDE			Not to Scale	Drawn I

Solder Area Component Outline

gct.co Sheet No.

