

Global Change Notification (GCN)

Product Family	Mini-Dimm	10660894		
		GCN Number		
Series	Multiple	December 05, 2014		
		Date Issued		
Reason For Change	Manufacturing Process Change			
Change Description	With this letter, we would like to inform a change in manufacturing process for Mini Dimm range of connectors of the following series 87940, 78001, 78035, 78081, 78457, 78574, 87783, 87824 and 87918. We will change from using loose clips to reel clips so as to enable automation of clip insertion assembly process. The change will provide a more stable and consistent result. There is no changes to the clips design and function. With this change, there is no change in the connector design and performance. Internal qualification and testing will be carried out to ensure the new process is qualified.			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.			
Reason For Short Notice Exception				
Assessment Of Change (How Product Will Be Qualified & Validated)	Qualification test at Molex			
Internal Molex Qualification Date (Planned Date Information Available)	December 10, 2014			
Sample Availability Date (Changed Part)	December 10, 2014			
Date of Implementation	June 05, 2015			
Method of Identifying Change	NA			
Recommended Replacement Parts	NA			
Last Time Buy Date for Obsolete Parts				
Last Time Ship Date for Obsolete Parts				

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com