INFORMATION NOTE



N° 012/17

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Data sheet update affecting products TLE4998C8(D), TLE4998S8(D), TLE4998P8(D)

Infineon Technologies AG Postal Address Headquarters: Am Campeon 1-12, D-85579 Neubiberg, Phone +49 (0)89 234-0 Chairman of the Supervisory Board: Wolfgang Mayrhuber Management Board: Dr. Reinhard Ploss (CEO), Dominik Asam, Dr. Helmut Gassel, Jochen Hanebeck Registered Office: Neubiberg Commercial Register Amtsgericht München HRB 126492

INFORMATION NOTE



N° 012/17

Data sheet update affecting productsTLE4998C8(D), TLE4998S8(D), TLE4998P8(D)

Products affected:	Sales Name	SP N°	OPN	Package
	TLE4998C8	SP000902764	TLE4998C8XUMA1	PG-TDSO-8-1
	TLE4998C8D	SP000902768	TLE4998C8DXUMA1	PG-TDSO-8-2
	TLE4998P8	SP000902772	TLE4998P8XUMA1	PG-TDSO-8-1
	TLE4998P8D	SP000902776	TLE4998P8DXUMA1	PG-TDSO-8-2
	TLE4998S8	SP000902780	TLE4998S8XUMA1	PG-TDSO-8-1
	TLE4998S8D	SP000902784	TLE4998S8DXUMA1	PG-TDSO-8-2

Detailed Change Information:

Subject:	Data sheet update affecting products productsTLE4998C8(D), TLE4998S8(D), TLE4998P8(D).			
Reason:	 Added Note / Test Condition to parameter Output noise (all products) Typo correction (only affecting products TLE4998C8(D) and TLE4998S8(D). 			
Description:	<u>Old</u> <u>New</u>			
	 Datasheet Rev. 1.0 Datasheet Rev 1.1 (for details refer to 4_cip17012 attached) 			
Product Identification:	Not applicable; data sheet update introduced only.			
Impact of Change:	No change neither of product nor process.			
Attachments:	Datasheet Rev. 1.1: 4_cip17012			
Intended start of delivery:	Valid with immediate effect.			

If you have any questions, please do not hesitate to contact your local Sales office.