



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: D010901

DATE: 30-Apr-2001

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1035-6	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035-8	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035C-401	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035C-401/T&R/	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035C-601	N/A	31-Dec-2001	30-Apr-2003	Part is leaded. Request information on lead-free version
Discontinuance	DS1035C-602	N/A	31-Dec-2001	30-Apr-2003	Part is leaded. Request information on lead-free version
Discontinuance	DS1035C-701	N/A	31-Dec-2001	30-Apr-2003	Part is leaded. Request information on lead-free version
Discontinuance	DS1035C-702	N/A	31-Dec-2001	30-Apr-2003	Part is leaded. Request information on lead-free version
Discontinuance	DS1035C-703	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035C-801	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035C-801/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035C-802	N/A	31-Dec-2001	30-Apr-2003	Part is leaded. Request information on lead-free version
Discontinuance	DS1035E-10	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035E-4	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035E-6	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035E-8	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035G-6	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035G-6/T&R	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035G-8	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035G-8/T&R	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035H-10	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035H-4	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035H-6	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035H-8	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035M-10	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035M-12	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 31-May-2001

Discontinuance	DS1035M-15	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035M-20	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035M-25	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035M-30	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035M-4	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035M-50	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035M-6	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035M-8	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-10	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-10/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-12	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-12/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-15	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-15/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-15/T&R/	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-20	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-20/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-20/T&R/	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-25	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-25/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-30	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-30/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-4	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035Z-50	N/A	31-Dec-2001	30-Apr-2003	The part was not released
Discontinuance	DS1035Z-6	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-6/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-6/T&R/	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-6/T&R/601	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-6/T&R/702	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-8	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-8/T&R	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-8/T&R/602	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-8/T&R/701	N/A	31-Dec-2001	30-Apr-2003	Part can no longer be manufactured
Discontinuance	DS1035Z-901	N/A	31-Dec-2001	30-Apr-2003	Part is leaded. Request information on lead-free version
Discontinuance	DS1035Z-902	N/A	31-Dec-2001	30-Apr-2003	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 31-May-2001