

Product End-of-Life (EOL) Notification	
AFFECTED PART NUMBER(S):	EOL No.
LZ1-00NW00-xxxx; LZ1-10NW00-xxxx; LZ1-30NW00-xxxx; LZ4-	00018
00NW08-xxxx; LZ4-40NW08-xxxx; LZ9-00NW00-xxxx; LZ9-	
JONW00-xxxx; LZ9-M0NW00-xxxx; LZC-00NW0R-xxxx; LZC-	
70NW0R-xxxx; LZC-C0NW0R-xxxx; LZP-00NW0R-xxxx; LZP-	
DONWOR-xxxx;	
PART DESCRIPTION:	DATE:
Neutral White emitters on LZ1, LZ4, LZ9, LZC, and LZP platform	4/30/2015
RECOMMENDED REPLACEMENT PART NUMBER(S):	
No replacement as a standard catalog product. May continue to be supported as a non-standard custom order on a case by case basis.	
REASON FOR EOL:	
Insufficient demand	
Insufficient demand	
LAST ORDER DATE:	LAST SHIPMENT DATE:
Existing orders will be fulfilled.	7/31/2015
DISPOSITION OF EXISTING INVENTORY:	
Use up current inventory	
NOTE:	
CONTACT PERSON: Ishita Goswami Product Manager	
651 River Oaks Parkway	
San Jose, CA 95134	
igoswami@ledengin.com	