

Date: November 7, 2016

PCN- 27816

Product Change Notification

Change Title:

SEALED XLR PANEL CONNECTORS (B_M__H SERIES) CHANGE OF ROHS COMPLIANCE STATUS

Product (s) Affected:

B3MAUH	B4MAUH	B5MAUH	B6MAUH	B7MAUH
B3MBAUH	B4MBAUH	B5MBAUH	B6MBAUH	B7MBAUH
B3MBGAUH	B4MBGAUH	B5MBGAUH	B6MBGAUH	B7MBGAUH
B3MBGH	B4MBGH	B5MBGH	B6MBGH	B7MBGH
B3MBH	B4MBH	B5MBH	B6MBH	B7MBH
B3MH	B4MH	B5MH	B6MH	B7MH

Reason for Change:

ROHS CERTIFICATE OF COMPLIANCE FOR THE EPOXY USED TO SEAL THE REAR OF THE CONNECTOR WAS RESCINDED BY SUPPLIER/MANUFACTURER.

Description of Change:

THE ABOVE LISTED PARTS ARE NOT ROHS COMPLIANT DUE TO THE EPOXY SEAL.

Estimated Schedule of Change:

IMMEDIATE

Customer Acknowledgement Form

(To be filled out by the customer and returned to Switchcraft)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: _____

Signature

(Electronic Signature is acceptable)

Print

Company: _____

Location: _____

Title: _____

Date: _____

Please return the signed PCN form to the attention of:

Switchcraft Customer Service Department

jpulliam@switchcraft.com

FAX: 773-792-2129